



09/761922

COFC

Docket No.: 06005/36804
(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:
Daniel D. Christensen et al.

Patent No.: 7,185,083

Issued: February 27, 2007

For: **METHOD AND APPARATUS FOR
IDENTIFYING AN I/O NETWORK IN A
PROCESS CONTROL SYSTEM**

**REQUEST FOR CERTIFICATE OF CORRECTION
PURSUANT TO 37 CFR 1.323**

Attention: Certificate of Correction Branch
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted typographical errors which should be corrected.

Certificate

NOV 07 2007

of Correction

On the First Page:

In the Abstract, page 25, line 9, Applicant error, "is response" should be-- in response --.

11/06/2007 MBLANCO 00000019 7185083

01 FC:1811

100.00 OP

In the Specification:

At page 12, line 14, Applicant error, "routine 84 and may" should be – routine 84 may --.

NOV 7 2007

In the Claims:

In the Examiner's Amendment, page 6, Claim 14, line 1, PTO error, "wherein the step of making the" should be -- wherein transmitting the --.

In the Examiner's Amendment, page 6, Claim 14, line 2, PTO error, "tag available on" should be -- tag on --.

In the Examiner's Amendment, page 6, Claim 15, line 1, PTO error, "wherein the step of making the" should be -- wherein transmitting the --.

In the Examiner's Amendment, page 6, Claim 15, line 2, PTO error, "tag available on" should be -- tag on --.

In the Examiner's Amendment, page 9, Claim 24, line 19, PTO error, "tae" should be -- tag --.

In the Examiner's Amendment, page 12, Claim 39, line 2, PTO error, "make" should be -- communicate --.

In the Examiner's Amendment, page 12, Claim 39, line 3, PTO error, "tag available on" should be -- tag on --.

In the Examiner's Amendment, page 17, Claim 59, line 2, PTO error, "steps 0" should be -- steps: --.

The errors were found in the application as filed by applicant. Our check in the amount of \$100.00 covering the fee set forth in 37 CFR 1.20(a) is enclosed.


The errors now sought to be corrected are inadvertent typographical errors the correction of which does not involve new matter or require reexamination.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction.

The Director is hereby authorized to charge any deficiency in the fees filed, asserted to be filed or which should have been filed herewith (or with any paper hereafter filed in this application by this firm) to our Deposit Account No. 13-2855, under Order No. 06005/36804.

Dated: November 1, 2007

Respectfully submitted,

By 
Roger A. Heppermann
Registration No.: 37,641
MARSHALL, GERSTEIN & BORUN LLP
233 S. Wacker Drive, Suite 6300
Sears Tower
Chicago, Illinois 60606-6357
(312) 474-6300
Attorney for Applicants

**UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION**Page 1 of 1

PATENT NO. : 7,185,083
APPLICATION NO. : 09/761,922
ISSUE DATE : February 27, 2007
INVENTOR(S) : Daniel D. Christensen et al.

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the First Page:

At field (57), line 13, "is response" should be-- in response --.

In the Specification:

At Column 8, lines 59-60, "routine 84 and may" should be -- routine 84 may --.

In the Claims:

At Column 11, line 63, "wherein the step of making the" should be -- wherein transmitting the --.

At Column 11, line 64, "tag available on" should be-- tag on --.

At Column 12, line 1, "wherein the step of making the" should be -- wherein transmitting the --.

At Column 12, line 2, "tag available on" should be -- tag on --.

At Column 12, line 59, "tae" should be -- tag --.

At Column 13, line 54, "make" should be-- communicate --.

At Column 13, lines 54-55, "tag available on" should be -- tag on --.

At Column 15, line 29, "steps 0" should be -- steps: --.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

Roger A. Heppermann
MARSHALL, GERSTEIN & BORUN LLP
233 S. Wacker Drive, Suite 6300
Sears Tower
Chicago, Illinois 60606-6357

NOV 7 2007